

This Page Is Inserted by IFW Operations  
and is not a part of the Official Record

## **BEST AVAILABLE IMAGES**

Defective images within this document are accurate representations of the original documents submitted by the applicant.

Defects in the images may include (but are not limited to):

- BLACK BORDERS
- TEXT CUT OFF AT TOP, BOTTOM OR SIDES
- FADED TEXT
- ILLEGIBLE TEXT
- SKEWED/SLANTED IMAGES
- COLORED PHOTOS
- BLACK OR VERY BLACK AND WHITE DARK PHOTOS
- GRAY SCALE DOCUMENTS

IMAGES ARE BEST AVAILABLE COPY.

**As rescanning documents *will not* correct images,  
please do not report the images to the  
Image Problems Mailbox.**







Fig. 1

**Fig.2**





*Fig.3*



*Fig.4*






Fig.5



*Fig.6*

Fig. 7






Fig.9





Fig.8



*Fig.10*







Fig. 11



*Fig. 12*



*Fig.13*



*Fig.14*




Fig.15




Fig. 16





Fig. 17A







Fig. 18A



**Fig. 18B**




Fig. 18C




Fig. 19A






Fig. 19B



**Fig. 20**

UPPER MOTOR SENSOR



178





Fig. 21A

FIG. 21B



178




Fig. 21B

HOME SENSOR  
UPPER






Fig.22

FROM FIG. 22





*Fig.24*




Fig.25





Fig. 26








Fig. 28A

FROM FIG. 28A



UPPER MOTORS  
102-1, 3, 5, 7, 9, 11

MINI DRW 1 - 6 MOTORS



*Fig.28B*




Fig. 29